

Operating Instruction (TPM-10)

Features

- LCD display.
- Insert design.
- Simple appearance.
- Two button batteries for longer use time.
- Especially applied in refrigerator, chiller, deepfreeze etc.

Technical parameter

- Temperature range: $-50^{\circ}\text{C} \sim +90^{\circ}\text{C}$
- Using environment: Temperature: $-5^{\circ}\text{C} \sim +50^{\circ}\text{C}$
Humidity: $5\% \sim 80\%$
- Accuracy: $\pm 1^{\circ}\text{C}$ ($-20^{\circ}\text{C} \sim +40^{\circ}\text{C}$)
 $\pm 2^{\circ}\text{C}$ ($-50^{\circ}\text{C} \sim -20^{\circ}\text{C}$, $+40^{\circ}\text{C} \sim +90^{\circ}\text{C}$)
- Resolution: $1(\leq -20^{\circ}\text{C})$ $0.1(>-20^{\circ}\text{C})$
- Power: two button battery (LR44, 1.5v)

Instruction

- Open the battery cover to put in two LR44 batteries correctly, pay attention to the polarity.
- Display when put in the batteries. Pls take out the batteries when not use for long time
- LCD display “--.- $^{\circ}\text{C}$ ” when temperature is lower than -50°C .
- Insert size: 46 x 26.6mm